


80% core deduction for damaged main
Servo housing.

5% core deduction if Fuel inlet fitting
missing.


20% core deduction if internal parts are
missing.

NOTE: Special fittings need to be removed
before returning, usually a restricted fitting
above fuel inlet, (not a Precision part).

60% core deduction for bad AMC, (AMC
units)



Please follow these guidelines for returning acceptable cores



5% core deduction for missing throttle
lever.

5% core deduction for missing fuel
outlet fitting.

5% core deduction for missing mixture
lever.

Flow Dividers: Complete and not disassembled.

NOTE: All fittings must be removed from flow dividers before returning.

Nozzles: Complete 2 piece nozzles with all parts; body, restrictor, screen & shroud.
50% core deduction for incomplete. \$50 for unacceptable nozzles.